

Number	Rev.	Ferrite Bias Supply MARK I Schematics (West Booster Gallery Type)	
0330.00-EC-5003	A	Carrier Generator 50 KHz Model Schematic	
0330.00-EB-5031		500 Amp solid state Contact 3 Phase current Monitor (MOD 1)	
0335.03-EE-5092		500 Amp solid state Contact SCR Gate Firing Transformer Schematic	
0335.03-EE-5093		500 Amp solid state Contact Thermistor Coupling Transformer Schematic	
0335.03-EE-5094		R.F. Systems BCPS-500A Solid State Contactor Control Unit	
0335.03-ED-5116		R.F. Systems Bias current Power Supply MK1 MkII Double Shielded RF Protected 3 phase transformer const.	
0335.03-EC-5118		R.F. Systems Bias current Power Supply Offset Power Supply Transformer Measurements	
0335.03-EB-5121	A	R.F. Systems Bias Current Power Supply SCR Gate Firing Card Schematic	
0335.03-EE-5123		R.F. Systems Bias Current Power Supply SCR Firing Circuit Schematic	
0330.00-EB-5124		500 Amp solid state Contact 3 Phase current Monitor (MOD 2)	
0335.03-EC-5125	A	R.F. Systems Bias Current Power Supply Shunt transistor (1 Bank) Schematic	
0335.03-EC-5162	B	R.F. Systems Bias Current Power Supply Phase Transformer Schematic	
0335.03-ED-5180		R.F. Systems Bias Current Pwr Sup. Overtemp Switch Junction box	
0335.03-ED-5200	B	R.F. Systems Bias Current Power Supply Flow Meter PC Card Schematic Replaced by Below	
0335.03-ED-180974		R.F. Systems Bias Current Power Supply Flow Meter PC Card Schematic	
0335.03-ED-5201	B	R.F. Systems Bias Current Power Supply Metering chassis Schematic Diagram	
0335.03-ED-5202	C	R.F. Systems Bias Current Power Supply Flow Meter Circuit Diagram	
0335.03-ED-5203	A	R.F. Systems Bias Current Power Supply Feed Thru Chassis Wiring Diagram	
0335.03-ED-5204	B	R.F. Systems Bias Current Power Supply Driver Power Supply wiring Diagram	
0335.03-ED-5215		R.F. Systems Bias Current Power Supply Offset Wiring Diagram	
0335.03-EC-5216		R.F. Systems Bias Current Power Supply 120V 60HZ AC wiring	
0335.03-EE-5219		R.F. Systems Bias Current Power Supply Transistor Driver Wiring Diagram	
0335.03-ED-5387		R.F. Systems Bias Current Power Supply Matrix card Schematic	
0335.03-EE-5411		R.F. Systems Bias Current Power Supply NAL MKI controller Chassis Schematic	
0335.03-ED-62272		R.F. Systems Bias Current Power Supply 50Khz Power Supply Wiring	LING DWG#46865
0335.03-ED-62273		R.F. Systems Bias Current Power Supply Control Unit Wiring	LING DWG#46864
0335.03-ED-62306		R.F. Systems Bias Current Power Supply SCR trigger PC Card Schematic	LING DWG#46612
0335.03-EC-62368		Schematic 50 KHz Power supply	

0335.03-EC-63050	A	R.F. Systems Bias Current Power Supply Ling & MKI Local Status Monitor Schematic
0335.03-EC-63104		R.F. Systems Bias Current Power Supply Flow Meter Test Circuit
0335.03-ED-63146		R.F. Systems Bias Current Power Supply NAL MKI LLE Assembly Drawing
0335.03-ED-63148		R.F. Systems Bias Current Power Supply NAL MKI LLE PC Card
0335.03-ED-63150		R.F. Systems Bias Current Power Supply NAL MKI BBE PC Card
0335.03-BC-63152		R.F. Systems Bias Current Power Supply NAL MKI BBE Assembly Drawing
0335.03-ED-63180		R.F. Systems Bias Current Power Supply 3 Phase Absent & Phase Sequence Indicator Schematic

Number Rev. Ferrite Bias Supply Mark II / NAL Schematics (East Booster Gallery Type)

0330.00-EC-5003	A	Carrier Generator 50 KHz Model Schematic
0330.00-EB-5031		500 Amp solid state Contact 3 Phase current Monitor (MOD 1)
0335.03-EE-5092		500 Amp solid state Contact SCR Gate Firing Transformer Schematic
0335.03-EE-5093		500 Amp solid state Contact Thermistor Coupling Transformer Schematic
0335.03-EB-5121	A	R.F. Systems Bias Current Power Supply SCR Gate Firing Card Schematic
0330.00-EB-5124		500 Amp solid state Contact 3 Phase current Monitor (MOD 2)
0335.03-EC-5125	A	R.F. Systems Bias Current Power Supply Shunt transistor (1 Bank) Schematic
0335.03-EC-5162	B	R.F. Systems Bias Current Power Supply Phase Transformer Schematic
0335.03-ED-5200	B	R.F. Systems Bias Current Power Supply Flow Meter PC Card Schematic Replaced by Below
0335.03-ED-180974		R.F. Systems Bias Current Power Supply Flow Meter PC Card Schematic
0335.06-EE-5337		R.F. Systems -100 to 2500A Prec Transductor Low Voltage Model MarkII Shield 1244 Schematic
0335.03-EB-5399	A	R.F. Systems Bias Current Power Supply MarkII Power Transistor Module (PTM)
0335.03-EE-22774	B	R.F. Systems Bias Current Power Supply (MarkII) SCR Firing Circuit Schematic
0335.03-EC-22822	B	R.F. Systems Bias Current Power Supply (MarkII) Driver Stage Schematic
0335.03-ED-22902	F	R.F. Systems Bias Current Power Supply MarkII Metering Panel Switch & Fault Indicator Wiring
0335.03-ED-22935	D	R.F. Systems Bias Current Power Supply MarkII Summing & Error Amplifiers Card B
0335.03-ED-22936	D	R.F. Systems Bias Current Power Supply MarkII P.C. 'A' Bus Bar Electronics
0335.03-ED-22937	F	R.F. Systems Bias Current Power Supply MarkII P.C. 'D' Protection Circuit
0335.03-EB-22967	B	R.F. Systems Bias Current Power Supply MarkII Wiring for Flow Switch
0335.03-EC-22987	A	R.F. Systems Bias Current Power Supply (MarkII) Offset Power Supply Schematic

-62014 P.C. Card Bin Wiring

0335.03-EC-62043	E	R.F. Systems Bias Current Power Supply MarkII 120V, 60 HZ, Distribution Wiring	
0335.03-EC-62064	A	R.F. Systems Bias Current Power Supply MarkII 480 V, Distribution Wiring	
0335.03-MC-62125		R.F. Systems Bias Current Power Supply MarkII Block Diagram	
0335.03-ED-62131	C	R.F. Systems Bias Current Power Supply Cross Connect Wiring	
0335.03-ED-62272		R.F. Systems Bias Current Power Supply 50Khz Power Supply Wiring	LING DWG#46865
0335.03-ED-62273		R.F. Systems Bias Current Power Supply Control Unit Wiring	LING DWG#46864
0335.03-EC-62368	A	R.F. Systems Bias Current Power Supply 50 KHz Power Supply Schematic	Ling DWG# 36383
0335.03-ED-62406	B	R.F. Systems Bias Current Power Supply MarkII P.C. Bin Wiring Diagram	
0335.03-EC-62766		R.F. Systems Bias Current Power Supply MarkII P.C. Board 'F' Schematic	
0335.03-ED-62782		R.F. Systems Bias Current Power Supply MarkII P.C. Board 'D' Protection Circuit Artwork	
0335.03-ED-62816		R.F. Systems Bias Current Power Supply MarkII SCR Firing Controller Chassis Wiring	
0335.03-EB-62900		R.F. Systems Bias Current Power Supply MarkII PTM Current Sensor	
0335.03-EC-62901	A	R.F. Systems Bias Current Power Supply MarkII Local Status Driver Board	
0335.03-ED-62907		R.F. Systems Bias Current Power Supply MarkII Matrix P.C. Card Schematic	
0335.03-ED-62908		R.F. Systems Bias Current Power Supply MarkII SCR trigger P.C. Card Schematic	
0335.03-EC-63104		R.F. Systems Bias Current Power Supply Flow Meter Test Circuit	

Number Rev.

Ferrite Bias Supply LING Schematics (Main Injector Type)

0330.00-EC-5003	A	Carrier Generator 50 KHz Model Schematic
0330.00-EB-5031		500 Amp solid state Contact 3 Phase current Monitor (MOD 1)
0335.03-EE-5092		500 Amp solid state Contact SCR Gate Firing Transformer Schematic
0335.03-EE-5093		500 Amp solid state Contact Thermistor Coupling Transformer Schematic
0335.03-EC-5118	A	R.F. Systems Bias current Power Supply Offset Power Supply Transformer Measurements
0335.03-EB-5121	A	R.F. Systems Bias Current Power Supply SCR Gate Firing Card Schematic

0330.00-EB-5124	500 Amp solid state Contact 3 Phase current Monitor (MOD 2)		
0335.03-EE-5123	R.F. Systems Bias Current Power Supply SCR Firing Circuit Schematic		
0335.03-EC-5125	A	R.F. Systems Bias Current Power Supply Shunt transistor (1 Bank) Schematic	
0335.03-EC-5162	B	R.F. Systems Bias Current Power Supply Phase Transformer Schematic	
0335.03-ED-5200	B	R.F. Systems Bias Current Power Supply Flow Meter PC Card Schematic Replaced by Below	
0335.03-ED-180974		R.F. Systems Bias Current Power Supply Flow Meter PC Card Schematic	
0335.03-ED-5204	B	R.F. Systems Bias Current Power Supply Driver Power Supply wiring Diagram	
0335.03-ED-5215		R.F. Systems Bias Current Power Supply Offset Wiring Diagram	
0335.03-ED-5217		R.F. Systems Bias Current Power Supply FeedBack Amplifier Circuit	
0335.03-ED-5218		R.F. Systems Bias Current Power Supply Active Filter Power Stages Schematic	
0335.03-ED-5387		R.F. Systems Bias Current Power Supply Matrix card Schematic	
0335.03-EE-5411		R.F. Systems Bias Current Power Supply NAL MKI controller Chassis Schematic	
0335.03-EC-22814		R.F. Systems Bias Current Power Supply (Ling) Flow Meter cabling	
0335.03-EC-62077		R.F. Systems Bias Current Power Supply Transducer Derippler Circuit-Ling	
0335.03-ED-62272		R.F. Systems Bias Current Power Supply 50Khz Power Supply Wiring	LING DWG#46865
0335.03-ED-62273		R.F. Systems Bias Current Power Supply Control Unit Wiring	LING DWG#46864
0335.03-ED-62306 -62307 -62361		R.F. Systems Bias Current Power Supply SCR trigger PC Card Schematic	LING DWG#46612
0335.03-EC-62368	A	R.F. Systems Bias Current Power Supply 50 KHz Power Supply Schematic	Ling DWG# 36383
0335.03-EC-62369	A	R.F. Systems Bias Current Power Supply, PreDriver Schematic	Ling DWG# 36397
0335.03-ED-62377	A	R.F. Systems Bias Current Power Supply (LING), Monitor Panel Schematic	Ling DWG# 46804
0335.03-ED-62378	A	R.F. Systems Bias Current Power Supply, Control & Interlock Schematic	Ling DWG# 46804
0335.03-EE-62385	A	Schematic Controller Chassis	Ling DWG# 50350-70-95
0335.03-EE-62386	A	Schematic Wiring Diagram Power Circuit	2 Sheets Ling DWG# 50481
0335.03-EC-63050	A	R.F. Systems Bias Current Power Supply, LING & MRKI Local Status Monitor	
0335.03-EC-63061		R.F. Systems Bias Current Power Supply Ling Protection Circuit Schematic	
0335.03-EC-63104		R.F. Systems Bias Current Power Supply Flow Meter Test Circuit	
0335.03-ED-63180		R.F. Systems Bias Current Power Supply 3 Phase Absent & Phase Sequence Indicator Schematic	